

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Fort Walton Staging Area	Facility Location ID:	FW01
Assessment Date :	7/13/2010	Incident Name :	BP Spill
Physical Location :	630 Martin Luther King Jr. Blvd. & Transit Station Rd.		
City, State :	Fort Walton Beach, FL	County :	Okaloosa

ASSESSMENT INFORMATION

General Site Information and Observations			
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/>	Yes	<input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?			
Additional Comments : Additional Comments: Only one R/O on site containing incident derived waste (oily sand) from the Okaloosa Island cleanup at Eglin AFB. Grab samples were taken from R/O #2227031 and place in two 8 oz. glass jars for purposes of running TCLP analysis for VOCs, SVOCs, metals and ignitability. No concerns regarding waste management practices were noted during the visit. New white R/O liner with draw string was being used. Liner was much more durable and stable than the more widely used black plastic liners. For more info on the product, contact Evan Taylor at the above number.			